
| City of Baltimore Wet Smoke and Dyed | Page 1 of 1 | |
|---|---------------------------------------|--|
| Sewershed: Gwynns Falls | Company: Savin | Date: <u>7/6/2009</u> |
| Test to be performed: Smoke Dyed Water X | Ground Condition: Dry ☑ Damp ☐ Wet ☐ | Supervisor: JAW |
| Manhole_ID: S05MM1008MH | Test ID: <u>D1032-034031</u> | Notification Made: NA (Residents, Fire, 311) |

Field Sketch: Show all manholes with Numbers, Blower Placement Locations, Sandbag or Isolation Locations, Street Names, Building Addresses and Locations, Defect Locations and Photo Numbers.



| Defect Loc | Obs_ClockFrom | Obs_ClockTo | Observation | Obs_Remarks |
|-------------|---------------|-------------|------------------|--------------------|
| 0 | | | Start of Survey | |
| 0 | | | Manhole | S05MM1008MH |
| 0 | | | Water Level | |
| 40.20000076 | | | Dye Test Visible | @ TF - downspout |
| 50 | | | End of Survey | DYE TEST COMPLETED |